



FNR 75 U

	220 V.					130 V.					110 V.				
	V <sub>1</sub>	V <sub>2</sub>	V <sub>3</sub>	V <sub>4</sub>	V <sub>5</sub>	V <sub>1</sub>	V <sub>2</sub>	V <sub>3</sub>	V <sub>4</sub>	V <sub>5</sub>	V <sub>1</sub>	V <sub>2</sub>	V <sub>3</sub>	V <sub>4</sub>	V <sub>5</sub>
V <sub>a</sub>	145	145	5	125	175/100	110	110	45	100	130/100	95	95	35	80	110/110
V <sub>g<sub>3</sub>-g<sub>5</sub></sub>	43	43	—	—	—	35	35	—	—	—	27	27	—	—	—
V <sub>g<sub>4</sub></sub>	—	145	—	—	—	—	110	—	—	—	—	95	—	—	—
V <sub>g<sub>1</sub></sub>	—	3	—	—	—	—	2	—	—	—	—	2	—	—	—
V <sub>c</sub>	2,3	2,3	3	—	100/165	1,6	1,6	2,2	—	105/120	1,2	1,2	1,8	—	105/105
V <sub>g<sub>2</sub></sub>	—	—	43	143	—	—	—	35	110	—	—	—	27	95	—